

The safety audits identifed several areas that require improvement. Overall, snow removal was identifed as one of the largest barriers at all stops. With Site C experiencing the largest fuctuations in maintenance, and Site B seeing the most maintenance. All of the bus stop locations were absent of bus shelters, yet included a bus stop sign. Site B and C lacked basic amenities such as garbage cans. Site A saw the most traf c of all the stops examined along

pedestrian and vehicle traf c.